



JetSym

Version update from V. 5.7.1 to V. 5.7.2

We automate your success

Jetter AG
Graeterstrasse 2
71642 Ludwigsburg,
Germany

Phone:
Switchboard +49 7141 2550-0
Sales +49 7141 2550-531
Technical hotline +49 7141 2550-444

E-mail:

Hotline	hotline@jetter
Sales	sales@jetter

Revision 1.00.1

2023-03-17

This document has been compiled by Jetter AG with due diligence based on the state of the art as known to them. Any revisions and technical advancements of our products are not automatically made available in a revised document. Jetter AG shall not be liable for any errors either in form or content, or for any missing updates, as well as for any damage or detriment resulting from such failure.

Table of contents

1	Fixed Software Bugs.....	1
1.1	OS update	1
1.1.1	OS update of Ethernet axes not possible.....	1
1.1.2	OS update via serial interface for JC-647.....	1
1.2	Motion setup	1
1.2.1	Crash for Scara groups.....	1
1.2.2	Moving Ethernet Axes by Drag and Drop.....	1
1.2.3	Download of Axis Parameter Files	1
2	Important notes.....	2
2.1	JetSym installation.....	2
2.1.1	.NET Framework 4.7.2.....	2

1 Fixed Software Bugs

This chapter describes the software bugs which have been fixed in the new software release. Please also refer to the **Open Issues** page in the online help.

1.1 OS update

1.1.1 OS update of Ethernet axes not possible

During the update process the message appeared that no axis was found for an MC-JM2xx OS and that the OS was incompatible with the axis.

1.1.2 OS update via serial interface for JC-647

OS update via serial interface at JC-647 was not possible.

1.2 Motion setup

1.2.1 Crash for Scara groups

Motion Setup for Scara groups, page Manual Operation - Circle: If the coordinate system level was changed and then a traverse was started, JetSym could crash.

1.2.2 Moving Ethernet Axes by Drag and Drop

Ethernet axes could not be repositioned in the hardware tree via drag and drop.

1.2.3 Download of Axis Parameter Files

The download of MC parameter files for controllers JC-440MC and JC-440EXT in connection with OS v1.10.0.00 failed.

2 Important notes

2.1 JetSym installation

The JetSym installer must be started with administrator rights to be able to license JetSym during the installation process.

2.1.1 .NET Framework 4.7.2

This version of JetSym requires .NET Framework 4.7.2.